

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
217					rk3588 ubuntu20.04 NoMachine		09/28/2023 05:35 AM	rk3588 ubuntu	system				wu wu	
258					rk3568 android11 lancher apk		04/07/2024 06:41 AM	rk3568-android	system					
254					PRO-RK3568-AHD-V11 rtc		03/16/2024 09:07 AM	rk3568-android	rtc					
250					a133 sdk		03/06/2024 08:21 AM	a133-android						
249					a311d usb		02/20/2024 02:27 AM	a311d-android	audio					
248					a133 a133 user-debug user		02/19/2024 06:12 AM	a133-android	system					
247					rk3588 buildroot pwr		02/20/2024 08:47 AM	rk3588-buildroot	system					
245					linux5.10 qt QTwebengine		02/27/2024 11:16 PM	rk3568-buildroot	system					
244					rk3568 rga imcvtcolor rga		01/15/2024 07:29 AM	rk356x						
240					t113 rs485		12/23/2023 02:05 AM	t113 -buildroot						
238					rk3588 ubuntu20.04		12/17/2023 11:53 PM	rk3588 ubuntu	display					
235					a311d ubuntu20.04 QT		12/23/2023 02:05 AM							
233					t507		12/04/2023 12:28 AM	t507-ubuntu	system					
232					rk3568 buildroot demo		11/23/2023 02:16 AM	rk3568-buildroot						
231					rk3568 Openharmony 4.0		11/23/2023 12:20 AM	rk356x						
230					rk1808 t8912 dsi hdmi mipi		11/18/2023 07:03 AM	rk1808-buildroot	display					
227					rd-rk3588 pcie		11/01/2023 11:56 PM	rk3588 ubuntu	pcie					
226					linux4.19 sdk linux5.10 sdk		10/29/2023 11:32 PM							
225					rk3568 ubuntu20.04		10/27/2023 12:19 AM	rk3568-ubuntu	system					
224					1106 IPC media Sample		10/19/2023 09:12 AM	rv1106						
223					rk3588 linux hdmi		03/06/2024 04:10 AM	rk3588-buildroot	display					
222					t507 linux		10/19/2023 12:01 AM	t507	touch					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
221					rk3328 linux		11/04/2023 07:45 AM	rk3328-buildroot	system					
220					rk3588 ubuntu 20.04		09/28/2023 09:20 AM	rk3588 ubuntu						
219					3308 mic uac		09/28/2023 09:49 AM	rk3308-buildroot	audio					
218					RK3308 mic		09/28/2023 07:18 AM	rk3308-buildroot	audio					
216					rk3568 android 4g		02/22/2024 02:30 AM	rk3568-android						
214					rk3588 ubuntu 20.04 gcc		09/20/2023 07:31 AM	rk3588 ubuntu	system					
213					rk3568 rtc		09/20/2023 10:37 AM	rk3568-ubuntu	rtc					
212					rk3588 isp		11/29/2023 01:23 AM	rk3588-buildroot	sensor					
211					rk3588 linux wifi		09/02/2023 06:06 AM	rk3588-debian	wifi					
210					rk3588 i2s		08/31/2023 12:01 AM	rk3588-buildroot	audio					
209					rk3588 linux5.10 can		01/11/2024 04:16 AM	rk3588 ubuntu	can					
207					rv1126		07/23/2023 11:55 PM	rv1126-buildroot						
206					1106 web sd		07/22/2023 01:15 AM	rv1106	system					
205					rk3588 uboot LPDDR4		11/01/2023 11:56 PM	rk3588 ubuntu						
204					t113 i2c1		06/15/2023 12:21 AM	t113-buildroot						
203					rk3588 ubuntu20.04 qt		11/29/2023 02:23 AM	rk3588 ubuntu	system					
202					rk3588 android		05/13/2023 06:09 AM	rk3588 android	wifi					
201					rk3399 android ota		05/09/2023 05:28 AM	rk3399-android	ota /sd /update					
200					t113 type-C otg usb_id_gpio		04/17/2023 11:51 AM	t113-buildroot						
199					s905d3 wifi		04/13/2023 05:48 AM	s905d3-android	wifi					
198					rk3588 GPU		09/25/2023 08:00 AM	rk3588 ubuntu	gpu					
197					rk3399		03/28/2023 11:33 AM	rk3399-buildroot	system					
196					rv1106 type-c adb		03/29/2024 12:48 AM	rv1106						
195					rk3588 edp		03/15/2023 11:40 AM	rk3568-ubuntu	display					
194					t507 wifi		03/15/2023 03:16 AM	t507-ubuntu	wifi					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
193					rv1126 logo		03/11/2023 05:56 AM	rv1126-ubuntu						
192					rk3568		03/09/2023 04:57 AM	rk3568-android						
191					rk3568 linux		03/08/2023 06:13 AM	rk3568-ubuntu	display					
190					t113 4g		03/07/2023 04:30 AM	t113 -buildroot						
189					t507 GPIO dts		03/04/2023 01:31 AM	t507-ubuntu	gpio					
188					rk3588 usb		03/03/2023 10:37 AM	rk3588 android	display					
187					rk3288 8.1		03/04/2023 06:50 AM	rk3288	uart					
186					rk3588 debian docker		02/18/2023 07:49 AM	rk3588-debian						
185					rv1126 sdk		02/11/2023 02:19 AM	rv1126-ubuntu						
184					rk3588 hdmi		03/15/2023 03:39 AM	rk3588 ubuntu	display					
183					rk3588 android12		01/13/2023 06:23 AM	rk3588 android						
182					rk3588 ubuntu 20.04 root		03/25/2023 06:15 AM	rk3588 ubuntu	system					
181					rk3588 app		01/10/2023 10:40 AM	rk3588 android	system					
180					rk3568 qt		01/10/2023 01:58 AM	rk3568-ubuntu						
179					t113 pwm		07/14/2023 01:14 AM	t113 -buildroot	pwm					
178					rk3288 android 8.1 wifi		01/07/2023 06:03 AM	rk3288						
177					rv1126		01/09/2023 12:40 AM	rv1126-ubuntu	system					
176					rk3566 cpu		01/07/2023 06:03 AM	rk3566-buildroot						
175					t507		05/25/2023 04:59 AM	t507-ubuntu						
174					rk3328 hdmi		01/02/2023 05:58 AM	rk3328-ubuntu	display					
173					rk		03/26/2024 09:17 AM	rk						
172					rk3568 usr/bin/startxde		12/30/2022 12:47 AM	rk3568-ubuntu	display					
171					rk3399 android8.1 apk		09/16/2023 07:09 AM	rk3399 -android						
170					t507 android		12/28/2022 07:31 AM	t509 -android10						
169					rk3568		01/07/2023 06:04 AM	rk3568-android	system					
168					rv1126 isp		12/26/2022 08:19 AM	rv1126-buildroot	display					
167					rk3566 echo 1000 > phy_lb_scan		08/17/2023 07:35 AM	rk3566-buildroot						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
166					rk3328 wifi		12/15/2022 08:01 AM	rk3328-buildroot	wifi/					
165					rk3568		12/14/2022 06:48 AM	rk3568-ubuntu						
164					t509		12/14/2022 01:15 AM	t509 -android10						
163					rk3588 can canfd		07/30/2023 11:19 PM	rk3588 ubuntu	can					
162					rk3568 gpio		09/18/2023 04:43 AM	rk3568-buildroot	gpio					
160					rk3328 mac		12/15/2022 11:36 AM	rk3328-ubuntu	system					
158					rk3568 gpio		05/13/2023 05:02 AM	rk3568-buildroot	gpio					
157					rk3399pro docker rknn		12/05/2022 01:15 AM	rk3399pro-linux	NPU					
156					rk3568 builroot python		11/29/2022 11:58 AM	rk3568-buildroot						
153					t507 buildroot video		11/25/2022 11:28 AM	t507	system					
152					rk3588		11/23/2023 12:46 AM	rk3588 ubuntu						
151					rk3566 ubuntu rknn		11/25/2022 12:49 AM	rk3566-ubuntu	NPU					
150					rk3588 rk		11/15/2022 07:52 AM	rk3588-debian						
148					rk1808 ntp		11/09/2022 10:56 AM	rk1808-buildroot	NPU					
146					t972 hdmi in		10/31/2022 11:28 AM	t972 -android9.0	display					
145					a311d2		11/10/2022 12:07 AM	A311D2-android	sensor					
144					rk3288 linux		08/14/2023 07:22 AM	rk3288						
143					rk1808 RNDIS		10/28/2022 05:59 AM	rk1808-buildroot						
142					Rk3128		03/29/2023 08:52 AM	rk3128-buildroot						
141					rk3588 pc		10/26/2022 06:54 AM	rk3588-buildroot						
140					rv1126 spi0 m0 m1		10/26/2022 06:54 AM	rv1126-ubuntu						
139					rv1126		10/24/2022 04:43 AM	rv1126-buildroot						
138					px30		10/24/2022 01:31 AM	px30 -android	system					
137					rk3568		01/02/2024 04:59 AM	rk3568-ubuntu						
136					rk3399 gps		10/20/2022 06:21 AM	rk3399 -android						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
135					rv1126 pip		10/14/2022 12:16 PM	rv1126-ubuntu						
134					rk3399 4G		10/14/2022 05:41 AM	rk3399-ubuntu						
133					px30 log		10/13/2022 11:55 AM	px30-buildroot	system					
132					T507 "POP"		12/02/2023 07:36 AM	t507	audio					
131					rk3399 android8.1 adb		10/10/2022 11:57 AM	rk3399 -android						
130					rk3399 android		10/09/2022 12:35 AM	rk3399 -android	display					
128					rk3399		09/28/2022 10:36 AM	rk3399-ubuntu	system					
126					rk3568 android		12/20/2023 01:15 AM	rk3568-ubuntu						
125					rk3588 5g		09/21/2022 06:17 AM	rk3588 android						
124					t507		09/17/2022 06:33 AM	t507-ubuntu	gpio					
123					rk3588 v4l2 gain control		10/07/2023 11:49 PM	rk3588-debian	sensor					
122					rk3588 buildroot eg		09/16/2022 09:11 AM	rk3588-buildroot						
121					rk3588		09/16/2022 06:50 AM	rk3588 ubuntu						
120					rv-1126		03/10/2023 01:17 AM	rv1126-buildroot	touch					
118					rk 3568 mmm		09/13/2022 09:33 AM	rk3568-android						
117					h6		09/08/2022 08:43 AM	h6 android	display					
116					rk3566 gpio		09/12/2023 07:24 AM	rk3566-android	gpio					
115					rk3588 hdmi rx		08/31/2023 05:50 AM	rk3588 ubuntu	display					
114					rk3566 ubuntu adb		09/27/2023 04:37 AM	rk3566-ubuntu	system					
113					px30 apk		09/02/2022 06:50 AM	px30 -android						
112					rk3568 pcie2.0		11/29/2023 05:01 AM	rk3568-buildroot	pcie					
111					rv1126 can		09/16/2022 09:01 AM	rv1126-buildroot	can					
110					rk3588 android ip		09/16/2022 07:31 AM	rk3588 android						
109					rv1126k 4G usb		09/05/2022 08:21 AM	rv1126-buildroot						
108					rk3399pro		08/31/2022 08:31 AM	rk3568-buildroot	system					
107					t113 buildroot		03/06/2023 07:57 AM	t113 -buildroot	system					
105					rk3128 pwm2		08/30/2022 07:10 AM	rk3128-android	pwm					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
103					6818 mac		09/07/2022 05:36 AM	6818-android						
102					rk3588 ubuntu 18.04 rtc		08/26/2022 08:50 AM	rk3588 ubuntu	rtc					
101					t113		08/26/2022 06:02 AM	t113 -buildroot	gpio					
100					t113 can		02/08/2023 06:20 AM	t113 -buildroot	can					
99					rk1808 npu		10/12/2022 07:38 AM	rk1808-buildroot	NPU					
98					rk3588 uboot		11/09/2023 06:33 AM	rk3588-debian	system					
97					rv1126 rv1109		08/25/2022 10:57 AM	rv1109-buildroot						
96					rk3568 linux debug		06/14/2023 07:29 AM	rk3568-buildroot						
95					t113		02/22/2023 04:43 AM	t113 -buildroot						
94					px30 log		08/23/2022 08:24 AM	px30 -android	display					
93					rk3399 emmc		08/22/2022 11:21 AM	rk3399-buildroot						
92					rv1126 gstreamer		08/22/2022 09:02 AM	rv1126-buildroot						
89					rk3568 pcie2.0 fpga		08/22/2022 10:27 AM	rk3568-buildroot	pcie					
87					rk3399		10/11/2022 12:53 AM	rk3399 -android						
86					rv1126 uboot		12/08/2023 05:46 AM	rv1126-ubuntu	system					
84					rk 3588 mpp		10/23/2023 06:38 AM	rk3588-debian						
82					rk3588 hdmi		08/20/2022 03:00 AM	rk3588 ubuntu	display					
81					rk3588 dts		08/18/2022 02:15 AM	rk3588 ubuntu						
80					rk3308		08/18/2022 01:08 AM	rk3308 -buildroot	system					
78					rk3568 i2s3		04/19/2023 05:49 AM	rk3568-ubuntu						
76					rk3566 rk3566 rk3568		08/16/2022 02:22 AM	rk3566-android						
75					rk3568 sd		04/28/2023 12:46 AM	rk3568-buildroot	system					
74					rk3568 gpu		11/09/2022 11:28 AM	rk3568-buildroot	gpu					
73					rk3588 parameter.txt		08/15/2022 06:54 AM	rk3588-buildroot						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
72					4		08/15/2022 06:16 AM	sensor	sensor					
70					rv1109 ubuntu yoloV5		08/15/2022 05:15 AM	rv1109-ubuntu						
69					t507 mipi dsi , can2		08/13/2022 06:12 AM	t507						
67					rk3399pro android 9.0		08/31/2022 09:17 AM	rk3399pro-android						
66					sdk npu 1.7		08/11/2022 08:52 AM	rk3399 -android	NPU					
63					rk3566 v2 .v3		11/01/2023 12:04 AM	rk3566-android	display					
62					rk3588		10/23/2023 08:41 AM	rk3588	sensor					
60					rk3588		08/18/2022 12:18 AM	rk3588 ubuntu						
59					t507		08/12/2022 12:12 PM	t507-ubuntu	gpio					
58					RK3288 Mipi		08/09/2022 11:45 AM	rk3288						
56					a311d2		08/09/2022 10:15 AM	A311D2-android	wifi					
55					rk3588 linux		08/09/2022 09:42 AM	rk3588						
54					rk3568 linux mdio bus name?		08/09/2022 09:02 AM	rk3568-buildroot						
53					rk3588 ubuntu V4l2		10/19/2023 04:48 AM	rk3588 ubuntu	sensor					
52					rk3399		08/24/2022 12:09 AM	rk3399 -android	system					
50					rv1126 buildroot		08/09/2022 02:22 AM	rv1126-buildroot						
49					rk3588		08/08/2022 11:02 AM	rk3588						
43					rk3588 linux evb		08/08/2022 07:44 AM	rk3588 ubuntu						
42					rk3588		06/09/2023 09:00 AM	rk3588 ubuntu						
40					rk3588		08/06/2022 06:10 AM	rk3588						
39					rk3566 adb		09/02/2022 11:13 AM	rk3566-android						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
35					rv1109 buildroot		08/05/2022 10:01 AM	rv1109-buildroot	system					
31					px30		09/23/2023 08:18 AM	px30-ubuntu	system					
29					px30 qt qmi		08/05/2022 06:26 AM	px30-ubuntu		#22: px30 QT	px30 QT			
28					rk3588 ubuntu v4l2, LIBJPEG_8.0		08/10/2022 01:28 AM	rk3588 ubuntu						
27					rk3588		08/05/2022 09:34 AM	rk3588 ubuntu	system					
23					rk3288 rk3288 usb-5v 2v		08/03/2022 11:17 AM	rk3288						
22					px30 QT		08/04/2022 06:38 AM	px30-ubuntu				0.00		
21					rk3568 npu		09/19/2022 02:12 AM	rk3568-buildroot	NPU					
19					rk3328 otg host		08/05/2022 09:36 AM	rk3328-ubuntu	ota /sd /update					
18					rv1126 ov13850		08/03/2022 09:29 AM	rv1126-buildroot	sensor					
17					rv1126 Linux ISP		08/05/2022 10:02 AM	rv1126-buildroot	isp					
16					rk3588		08/08/2022 08:30 AM	rk3588 android	display			0.00		
15					rk3588 ubuntu usb		08/05/2022 09:35 AM	rk3588 ubuntu	audio					
13					a40i mplayer		08/18/2022 12:21 AM	a40i-buildroot	display					
12					rk3588 ping		09/27/2022 04:38 AM	rk3588 ubuntu						
11					hi3516dv 300 3.3v		08/05/2022 10:06 AM	hi3516dv300_v20						
10					t113 ping		12/01/2022 07:23 AM	t113-buildroot						
9					rk3399 ov13850		08/16/2022 09:24 AM	rk3399-ubuntu	sensor					
7					rv1126 buildroot IP		07/13/2023 05:54 AM	rv1126-buildroot						
6					t113 Ubuntu ssh		10/14/2022 07:19 AM	t113-buildroot	ssh					
256					rk3588		03/25/2024 04:22 AM	rk3588 ubuntu	display					
255					rk3588 Android13 HDMI		03/18/2024 06:54 AM	rk3588 android	system					
253					rk1808 rtc		03/08/2024 07:07 AM	rk1808-buildroot	rtc					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
251					rv1126 lane in		03/07/2024 07:22 AM	rv1126-buildroot	audio					
246					rv1109-rv1126 Ubuntu20.04 docker		01/19/2024 05:02 AM	rv1126-ubuntu						
243					3568 Android		01/05/2024 08:49 AM	rk3568-android						
242					ubuntu20.04		01/04/2024 01:43 AM	rk3588 ubuntu						
241					rp3128 OTA		12/29/2023 07:43 AM	rk3128-buildroot						
239					t509 Android a133 Android a311d2 Android app		12/23/2023 08:34 AM	t509 -android10						
237					3588		12/14/2023 06:36 AM	rk3588-buildroot	audio					
236					3588 buildroot		12/09/2023 04:53 AM	rk3588-buildroot						
234					gpio-----ubootgpio		12/04/2023 04:26 AM	rk3588-buildroot	gpio					
229					RP-BOX-RK3399 Android APP		11/07/2023 01:00 AM	rk3399 -android						
228					pro-box-t507		11/05/2023 11:29 PM	t507-ubuntu						
106					rk3588 sd		01/30/2024 09:02 AM	rk3588 ubuntu	SD					
90					t507		08/22/2022 10:59 AM	t507-ubuntu						
208					rk3568 mic		07/27/2023 02:17 AM	rk3568-buildroot	audio					
155					px30 android8.1 ota		08/24/2023 06:45 AM	px30 -android						
32					rk3568 libdrm/build.sh		08/08/2022 07:53 AM	rk3568-buildroot						
77					rk3568 hdmi hdmi		08/16/2022 06:07 AM	rk3568-ubuntu	display					
45					rk3568		08/08/2022 09:17 AM	rk3568-buildroot						
41					rk3399 ubuntu 16.04		08/09/2022 10:17 AM	rk3399-ubuntu						
37					px30 gpio		08/09/2022 07:56 AM	px30 -android	gpio					
71					ov13850		08/16/2022 08:34 AM	sensor	sensor					
68					rk3128 uvc		08/16/2022 09:15 AM	rk3128-android	sensor					
61					rk3568 buildroot i2cm0m1?		08/10/2022 07:26 AM	rk3568-buildroot	I2C					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
57					a311d2		08/10/2022 07:29 AM	A311D2-android						
30					rk3588		08/06/2022 12:49 AM	rk3588 android						
25					t507 linux		08/05/2022 11:43 AM	t507-ubuntu	touch					
51					rv1126		08/09/2022 05:21 AM	rv1126-buildroot						
34					rv1126 imx415		08/09/2022 05:25 AM	rv1126-buildroot	sensor					
159					rk3568 ptp1588		12/08/2022 05:37 AM	rk3568-buildroot						
119					rk3588 usb3.0		09/15/2022 12:36 AM	rk3588 ubuntu	display					
64					rk3588 ubuntu 18.04 demo		08/17/2022 01:16 AM	rk3588 ubuntu						
46					rk3588 RkVideoPlayer-8.1+(8.1)rtsp		08/09/2022 01:14 AM	rk3588 android		#16: rk3588	rk3588			
14					rk3588 isp		08/08/2022 07:14 AM	rk3588 ubuntu	isp					
85					rk3588 hdmi		08/23/2022 01:37 AM	rk3588-buildroot	display					
65					rk3588 ubuntu18.04 OpenCV3.4.6+opencv_contrib 3.4.6		01/03/2023 12:06 PM	rk3588 ubuntu						
26					t113		08/05/2022 06:32 AM	t113-buildroot						
154					a40i		11/26/2022 03:00 AM	a40i-buildroot						
79					rk3399 edp		08/19/2022 08:21 AM	rk3399	display					
44					rk3568 4G		08/19/2022 07:46 AM	rk3568-android						
36					t507linux		08/06/2022 06:45 AM	t507-ubuntu						
259					3128		04/07/2024 07:59 AM	rk3128-android	system					
257					rv1126		03/27/2024 12:10 AM	rv1126-ubuntu	system					
215							09/26/2023 11:26 PM							
161					rk3588		12/09/2022 05:07 AM	rk3588-debian	system					
149					rk3588 ip		11/11/2022 11:04 AM	rk3588-buildroot						
147					RK3399 Rtmp		11/02/2022 07:55 AM	rk3399-ubuntu	wifi					
129					rv1126 uvcsdk		09/27/2022 08:52 AM	rv1109-buildroot	sensor					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
127	rk3568	rk3568	Open	High	rk3568 ubuntu	rk3568	09/23/2022 02:24 AM	rk3568-ubuntu	system					
91	rk3399	rk3399	Open	High	rk3399 ubuntu	rk3399	08/22/2022 07:26 AM	rk3399-ubuntu	system					
88	rk3588	rk3588	Open	High	rk3588 androidDP	rk3588	08/22/2022 02:44 AM	rk3588 android	display					
83	rk3588	rk3588	Open	High	rk3588 linux rtsp demo		08/19/2022 05:45 AM	rk3588						
48	rv1126	rv1126	Open	High	rv1126 -rv1109 809		08/08/2022 10:02 AM	rv1109-buildroot	audio					
38	rv1126	rv1126	Open	High	rv1126 gpio	rv1126	08/06/2022 02:48 AM	rv1126-buildroot	gpio					