

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
259					3128		04/07/2024 07:59 AM	rk3128-android	system					
258					rk3568 android11		04/07/2024 06:41 AM	rk3568-android	system					
257					rv1126		03/27/2024 12:10 AM	rv1126-ubuntu	system					
256					rk3588		03/25/2024 04:22 AM	rk3588 ubuntu	display					
255					rk3588 Android13		03/18/2024 06:54 AM	rk3588 android	system					
254					PRO-RK3568-AHD-V11		03/16/2024 09:07 AM	rk3568-android	rtc					
253					rk1808 rtc		03/08/2024 07:07 AM	rk1808-buildroot	rtc					
251					rv1126 lane in		03/07/2024 07:22 AM	rv1126-buildroot	audio					
250					a133		03/06/2024 08:21 AM	a133-android						
249					a311d		02/20/2024 02:27 AM	a311d-android	audio					
248					a133		02/19/2024 06:12 AM	a133-android	system					
247					rk3588 buildroot		02/20/2024 08:47 AM	rk3588-buildroot	system					
246					rv1109-rv1126 Ubuntu20.04		01/19/2024 05:02 AM	rv1126-ubuntu						
245					linux5.10 qt		02/27/2024 11:16 PM	rk3568-buildroot	system					
244					rk3568 rga		01/15/2024 07:29 AM	rk356x						
243					3568 Android		01/05/2024 08:49 AM	rk3568-android						
242					ubuntu20.04		01/04/2024 01:43 AM	rk3588 ubuntu						
241					rp3128 OTA		12/29/2023 07:43 AM	rk3128-buildroot						
240					t113 rs485		12/23/2023 02:05 AM	t113 -buildroot						
239					t509 Android		12/23/2023 08:34 AM	t509 -android10						
238					rk3588 ubuntu20.04		12/17/2023 11:53 PM	rk3588 ubuntu	display					
237					3588		12/14/2023 06:36 AM	rk3588-buildroot	audio					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
236					3588 buildroot		12/09/2023 04:53 AM	rk3588-buildroot						
235					a311d ubuntu20.04 QT		12/23/2023 02:05 AM							
234					gpio-----ubootgpio		12/04/2023 04:26 AM	rk3588-buildroot	gpio					
233					t507		12/04/2023 12:28 AM	t507-ubuntu	system					
232					rk3568 buildroot demo		11/23/2023 02:16 AM	rk3568-buildroot						
231					rk3568 Openharmony4.0		11/23/2023 12:20 AM	rk356x						
230					rk1808 It8912 dsihdmi mipi		11/18/2023 07:03 AM	rk1808-buildroot	display					
229					RP-BOX-RK3399 AndroidAPP		11/07/2023 01:00 AM	rk3399 -android						
228					pro-box-t507		11/05/2023 11:29 PM	t507-ubuntu						
227					rd-rk3588 pcie		11/01/2023 11:56 PM	rk3588 ubuntu	pcie					
226					linux4.19 sdk linux5.10 sdk		10/29/2023 11:32 PM							
225					rk3568 ubuntu20.04		10/27/2023 12:19 AM	rk3568-ubuntu	system					
224					1106 IPC mediaSample		10/19/2023 09:12 AM	rv1106						
223					rk3588 linux hdmi		03/06/2024 04:10 AM	rk3588-buildroot	display					
222					t507 linux		10/19/2023 12:01 AM	t507	touch					
221					rk3328 linux		11/04/2023 07:45 AM	rk3328-buildroot	system					
220					rk3588 ubuntu 20.04		09/28/2023 09:20 AM	rk3588 ubuntu						
219					3308 mic uac		09/28/2023 09:49 AM	rk3308-buildroot	audio					
218					RK3308 mic		09/28/2023 07:18 AM	rk3308-buildroot	audio					
217					rk3588 ubuntu20.04 NoMachine		09/28/2023 05:35 AM	rk3588 ubuntu	system				wu wu	
216					rk3568 android 4g		02/22/2024 02:30 AM	rk3568-android						
215							09/26/2023 11:26 PM							
214					rk3588 ubuntu 20.04 gcc		09/20/2023 07:31 AM	rk3588 ubuntu	system					
213					rk3568 rtc		09/20/2023 10:37 AM	rk3568-ubuntu	rtc					
212					rk3588 isp		11/29/2023 01:23 AM	rk3588-buildroot	sensor					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
211					rk3588 linux wifi		09/02/2023 06:06 AM	rk3588-debian	wifi					
210					rk3588 i2s		08/31/2023 12:01 AM	rk3588-buildroot	audio					
209					rk3588 linux5.10 can		01/11/2024 04:16 AM	rk3588 ubuntu	can					
208					rk3568 mic		07/27/2023 02:17 AM	rk3568-buildroot	audio					
207					rv1126		07/23/2023 11:55 PM	rv1126-buildroot						
206					1106 web sd		07/22/2023 01:15 AM	rv1106	system					
205					rk3588 uboot LPDDR4		11/01/2023 11:56 PM	rk3588 ubuntu						
204					t113 i2c1		06/15/2023 12:21 AM	t113 -buildroot						
203					rk3588 ubuntu20.04 qt		11/29/2023 02:23 AM	rk3588 ubuntu	system					
202					rk3588 android		05/13/2023 06:09 AM	rk3588 android	wifi					
201					rk3399 android ota		05/09/2023 05:28 AM	rk3399 -android	ota /sd /update					
200					t113 type-C otg usb_id_gpio		04/17/2023 11:51 AM	t113 -buildroot						
199					s905d3 wifi		04/13/2023 05:48 AM	s905d3-android	wifi					
198					rk3588 GPU		09/25/2023 08:00 AM	rk3588 ubuntu	gpu					
197					rk3399		03/28/2023 11:33 AM	rk3399-buildroot	system					
196					rv1106 type-c adb		03/29/2024 12:48 AM	rv1106						
195					rk3588 edp		03/15/2023 11:40 AM	rk3568-ubuntu	display					
194					t507 wifi		03/15/2023 03:16 AM	t507-ubuntu	wifi					
193					rv1126 logo		03/11/2023 05:56 AM	rv1126-ubuntu						
192					rk3568		03/09/2023 04:57 AM	rk3568-android						
191					rk3568 linux		03/08/2023 06:13 AM	rk3568-ubuntu	display					
190					t113 4g		03/07/2023 04:30 AM	t113 -buildroot						
189					t507 GPIO dts		03/04/2023 01:31 AM	t507-ubuntu	gpio					
188					rk3588 usb		03/03/2023 10:37 AM	rk3588 android	display					
187					rk3288 8.1 32		03/04/2023 06:50 AM	rk3288	uart					
186					rk3588 debian docker		02/18/2023 07:49 AM	rk3588-debian						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
185					rv1126 sdk		02/11/2023 02:19 AM	rv1126-ubuntu						
184					rk3588 hdmi		03/15/2023 03:39 AM	rk3588 ubuntu	display					
183					rk3588 android12		01/13/2023 06:23 AM	rk3588 android						
182					rk3588 ubuntu 20.04		03/25/2023 06:15 AM	rk3588 ubuntu	system					
181					rk3588 app		01/10/2023 10:40 AM	rk3588 android	system					
180					rk3568 qt		01/10/2023 01:58 AM	rk3568-ubuntu						
179					t113 pwm		07/14/2023 01:14 AM	t113 -buildroot	pwm					
178					rk3288 android 8.1		01/07/2023 06:03 AM	rk3288						
177					rv1126		01/09/2023 12:40 AM	rv1126-ubuntu	system					
176					rk3566 cpu		01/07/2023 06:03 AM	rk3566-buildroot						
175					t507		05/25/2023 04:59 AM	t507-ubuntu						
174					rk3328 hdmi		01/02/2023 05:58 AM	rk3328-ubuntu	display					
173					rk		03/26/2024 09:17 AM	rk						
172					rk3568 usr/bin/startlxde		12/30/2022 12:47 AM	rk3568-ubuntu	display					
171					rk3399 android8.1		09/16/2023 07:09 AM	rk3399 -android						
170					t507 android		12/28/2022 07:31 AM	t509 -android10						
169					rk3568		01/07/2023 06:04 AM	rk3568-android	system					
168					rv1126 isp		12/26/2022 08:19 AM	rv1126-buildroot	display					
167					rk3566 echo 1000 > phy_lb_scan		08/17/2023 07:35 AM	rk3566-buildroot						
166					rk3328 wifi		12/15/2022 08:01 AM	rk3328-buildroot	wifi					
165					rk3568		12/14/2022 06:48 AM	rk3568-ubuntu						
164					t509		12/14/2022 01:15 AM	t509 -android10						
163					rk3588 can		07/30/2023 11:19 PM	rk3588 ubuntu	can					
162					rk3568 gpio		09/18/2023 04:43 AM	rk3568-buildroot	gpio					
161					rk3588		12/09/2022 05:07 AM	rk3588-debian	system					
160					rk3328 mac		12/15/2022 11:36 AM	rk3328-ubuntu	system					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
159					rk3568 ptp1588		12/08/2022 05:37 AM	rk3568-buildroot						
158					rk3568 gpio		05/13/2023 05:02 AM	rk3568-buildroot	gpio					
157					rk3399pro docker rknn		12/05/2022 01:15 AM	rk3399pro-linux	NPU					
156					rk3568 builroot python		11/29/2022 11:58 AM	rk3568-buildroot						
155					px 30 android8.1 ota		08/24/2023 06:45 AM	px30 -android						
154					a40i		11/26/2022 03:00 AM	a40i-buildroot						
153					t507 buildroot video		11/25/2022 11:28 AM	t507	system					
152					rk3588		11/23/2023 12:46 AM	rk3588 ubuntu						
151					rk3566 ubunt rknn		11/25/2022 12:49 AM	rk3566-ubuntu	NPU					
150					rk3588 rk		11/15/2022 07:52 AM	rk3588-debian						
149					rk3588 ip		11/11/2022 11:04 AM	rk3588-buildroot						
148					rk1808 ntp		11/09/2022 10:56 AM	rk1808-buildroot	NPU					
147					RK3399 Rtmp		11/02/2022 07:55 AM	rk3399-ubuntu	wifi					
146					t972 hdmi in		10/31/2022 11:28 AM	t972 -android9.0	display					
145					a311d2		11/10/2022 12:07 AM	A311D2-android	sensor					
144					rk3288 linux		08/14/2023 07:22 AM	rk3288						
143					rk1808 RNDIS		10/28/2022 05:59 AM	rk1808-buildroot						
142					Rk3128		03/29/2023 08:52 AM	rk3128-buildroot						
141					rk3588 pc		10/26/2022 06:54 AM	rk3588-buildroot						
140					rv1126 spi0 m0 m1		10/26/2022 06:54 AM	rv1126-ubuntu						
139					rv1126		10/24/2022 04:43 AM	rv1126-buildroot						
138					px30		10/24/2022 01:31 AM	px30 -android	system					
137					rk3568		01/02/2024 04:59 AM	rk3568-ubuntu						
136					rk3399 gps		10/20/2022 06:21 AM	rk3399 -android						
135					rv1126 pip		10/14/2022 12:16 PM	rv1126-ubuntu						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
134	0000	00	00	00	rk3399 4G 0000		10/14/2022 05:41 AM	rk3399-ubuntu	00				0 0	
133	0000	00	00	00	px30 0000log		10/13/2022 11:55 AM	px30-buildroot	system				0 0	
132	0000	00	00	00	T507 000000000000000000000000"POP"		12/02/2023 07:36 AM	t507	audio				0 0	
131	0000	00	00	00	rk3399 android8.1 adb 0000000	000 0	10/10/2022 11:57 AM	rk3399 -android	00				0 0	
130	0000	00	00	00	rk3399 android 0000		10/09/2022 12:35 AM	rk3399 -android	display				0 0	
129	0000	00	00	00	rv1126 uvcsdk000000000000		09/27/2022 08:52 AM	rv1109-buildroot	sensor					
128	0000	00	00	00	rk3399 0000000000		09/28/2022 10:36 AM	rk3399-ubuntu	system				0 0	
127	0000	00	00	00	rk3568 000000	0 00	09/23/2022 02:24 AM	rk3568-ubuntu	system					
126	0000	00	00	00	rk3568 0000 0android0000000000		12/20/2023 01:15 AM	rk3568-ubuntu	00				0 0	
125	0000	00	00	00	rk3588 00005g00		09/21/2022 06:17 AM	rk3588 android	00				0 0	
124	0000	00	00	00	t507 0000000000000000		09/17/2022 06:33 AM	t507-ubuntu	gpio				0 0	
123	0000	00	00	00	rk3588 0000 v4l2 000000gain 0 control	0 00	10/07/2023 11:49 PM	rk3588-debian	sensor				0 0	
122	0000	00	00	00	rk3588 buildroot egl0000000000		09/16/2022 09:11 AM	rk3588-buildroot	00				0 0	
121	0000	00	00	00	rk3588 0000		09/16/2022 06:50 AM	rk3588 ubuntu	0000				0 0	
120	0000	00	00	00	rv-1126 00 00	00 0	03/10/2023 01:17 AM	rv1126-buildroot	touch				0 0	
119	0000	00	00	00	rk3588 00usb3.00000000	0 00	09/15/2022 12:36 AM	rk3588 ubuntu	display				0 00	
118	0000	00	00	00	rk 3568 00mmm00000000000		09/13/2022 09:33 AM	rk3568-android	0000				0 0	
117	0000	00	00	00	h6 0000000000		09/08/2022 08:43 AM	h6 android	display				0 0	
116	0000	00	00	00	rk3566 00gpio0000		09/12/2023 07:24 AM	rk3566-android	gpio				0 0	
115	0000	00	00	00	rk3588 hdmi rx 0000		08/31/2023 05:50 AM	rk3588 ubuntu	display				0 0	
114	0000	00	00	00	rk3566 ubuntu 00000000adb00		09/27/2023 04:37 AM	rk3566-ubuntu	system				0 0	
113	0000	00	00	00	px30 0000000000apk		09/02/2022 06:50 AM	px30 -android	00				0 0	
112	0000	00	00	00	rk3568 pcie2.0 0000		11/29/2023 05:01 AM	rk3568-buildroot	pcie				0 0	
111	0000	00	00	00	rv1126 can 0000	00 0	09/16/2022 09:01 AM	rv1126-buildroot	can				0 0	
110	0000	00	00	00	rk3588 android 0000000000ip	000 0	09/16/2022 07:31 AM	rk3588 android	00				0 0	
109	0000	00	00	00	rv1126k 4G 0usb 000000	00 0	09/05/2022 08:21 AM	rv1126-buildroot	00				0 0	

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
108					rk3399pro		08/31/2022 08:31 AM	rk3568-buildroot	system					
107					t113 builroot		03/06/2023 07:57 AM	t113 -buildroot	system					
106					rk3588 sd		01/30/2024 09:02 AM	rk3588 ubuntu	SD					
105					rk3128 pwm2		08/30/2022 07:10 AM	rk3128-android	pwm					
103					6818 mac		09/07/2022 05:36 AM	6818-android						
102					rk3588 ubuntu 18.04 rtc		08/26/2022 08:50 AM	rk3588 ubuntu	rtc					
101					t113		08/26/2022 06:02 AM	t113 -buildroot	gpio					
100					t113 can		02/08/2023 06:20 AM	t113 -buildroot	can					
99					rk1808 npu		10/12/2022 07:38 AM	rk1808-buildroot	NPU					
98					rk3588 uboot		11/09/2023 06:33 AM	rk3588-debian	system					
97					rv1126 rv1109		08/25/2022 10:57 AM	rv1109-buildroot						
96					rk3568 linux debug		06/14/2023 07:29 AM	rk3568-buildroot						
95					t113		02/22/2023 04:43 AM	t113 -buildroot						
94					px30 log		08/23/2022 08:24 AM	px30 -android	display					
93					rk3399 emmc		08/22/2022 11:21 AM	rk3399-buildroot						
92					rv1126 gstreamer		08/22/2022 09:02 AM	rv1126-buildroot						
91					rk3399 ubuntu		08/22/2022 07:26 AM	rk3399-ubuntu	system					
90					t507		08/22/2022 10:59 AM	t507-ubuntu						
89					rk3568 pcie2.0 fpga		08/22/2022 10:27 AM	rk3568-buildroot	pcie					
88					rk3588 androidDP		08/22/2022 02:44 AM	rk3588 android	display					
87					rk3399		10/11/2022 12:53 AM	rk3399 -android						
86					rv1126 uboot		12/08/2023 05:46 AM	rv1126-ubuntu	system					
85					rk3588 hdmi		08/23/2022 01:37 AM	rk3588-buildroot	display					
84					rk 3588 mpp		10/23/2023 06:38 AM	rk3588-debian						
83					rk3588 linux rtsp demo		08/19/2022 05:45 AM	rk3588						
82					rk3588 hdmi		08/20/2022 03:00 AM	rk3588 ubuntu	display					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
81					rk3588 dtsc,dtsc		08/18/2022 02:15 AM	rk3588 ubuntu						
80					rk3308		08/18/2022 01:08 AM	rk3308-buildroot	system					
79					rk3399 edp		08/19/2022 08:21 AM	rk3399	display					
78					rk3568 i2s3		04/19/2023 05:49 AM	rk3568-ubuntu						
77					rk3568 hdmi hdmi		08/16/2022 06:07 AM	rk3568-ubuntu	display					
76					rk3566 rk3566 rk3568		08/16/2022 02:22 AM	rk3566-android						
75					rk3568 sd		04/28/2023 12:46 AM	rk3568-buildroot	system					
74					rk3568 gpu		11/09/2022 11:28 AM	rk3568-buildroot	gpu					
73					rk3588 parameter.txt		08/15/2022 06:54 AM	rk3588-buildroot						
72					4		08/15/2022 06:16 AM	sensor	sensor					
71					ov13850		08/16/2022 08:34 AM	sensor	sensor					
70					rv1109 ubuntu yolov5		08/15/2022 05:15 AM	rv1109-ubuntu						
69					t507 mipi dsi , can2		08/13/2022 06:12 AM	t507						
68					rk3128 uvc		08/16/2022 09:15 AM	rk3128-android	sensor					
67					rk3399pro android 9.0 adb		08/31/2022 09:17 AM	rk3399pro-android						
66					sdk npu 1.7		08/11/2022 08:52 AM	rk3399 -android	NPU					
65					rk3588 ubuntu18.04 OpenCV3.4.6+ opencv_contrib 3.4.6		01/03/2023 12:06 PM	rk3588 ubuntu						
64					rk3588 ubuntu 18.04 demo		08/17/2022 01:16 AM	rk3588 ubuntu						
63					rk3566 v2 .v3		11/01/2023 12:04 AM	rk3566-android	display					
62					rk3588		10/23/2023 08:41 AM	rk3588	sensor					
61					rk3568 buildroot i2cm0m1?		08/10/2022 07:26 AM	rk3568-buildroot	I2C					
60					rk3588 8		08/18/2022 12:18 AM	rk3588 ubuntu						
59					t507		08/12/2022 12:12 PM	t507-ubuntu	gpio					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
58					RK3288 Mipi		08/09/2022 11:45 AM	rk3288						
57					a311d2		08/10/2022 07:29 AM	A311D2-android						
56					a311d2		08/09/2022 10:15 AM	A311D2-android	wifi					
55					rk3588 linux		08/09/2022 09:42 AM	rk3588						
54					rk3568 linux mdio bus name?		08/09/2022 09:02 AM	rk3568-buildroot						
53					rk3588 ubuntu V4l2 AHD		10/19/2023 04:48 AM	rk3588 ubuntu	sensor					
52					rk3399 20		08/24/2022 12:09 AM	rk3399 -android	system					
51					rv1126		08/09/2022 05:21 AM	rv1126-buildroot						
50					rv1126 buildroot glibc		08/09/2022 02:22 AM	rv1126-buildroot						
49					rk3588 rd-rk3588.dts		08/08/2022 11:02 AM	rk3588						
48					rv1126 -rv1109 809		08/08/2022 10:02 AM	rv1109-buildroot	audio					
45					rk3568		08/08/2022 09:17 AM	rk3568-buildroot						
44					rk3568 4G		08/19/2022 07:46 AM	rk3568-android						
43					rk3588 linux evb rk3588-linux-sdk-beat-v0.1.0 sdk		08/08/2022 07:44 AM	rk3588 ubuntu						
42					rk3588 multi		06/09/2023 09:00 AM	rk3588 ubuntu						
41					rk3399 ubuntu 16.04		08/09/2022 10:17 AM	rk3399-ubuntu						
40					rk3588 cmake-qt-gui update		08/06/2022 06:10 AM	rk3588						
39					rk3566 adb		09/02/2022 11:13 AM	rk3566-android						
38					rv1126 gpio		08/06/2022 02:48 AM	rv1126-buildroot	gpio					
37					px30 gpio		08/09/2022 07:56 AM	px30 -android	gpio					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
36					t507linux		08/06/2022 06:45 AM	t507-ubuntu						
35					rv1109 buildroot		08/05/2022 10:01 AM	rv1109-buildroot	system					
34					rv1126 imx415		08/09/2022 05:25 AM	rv1126-buildroot	sensor					
32					rk3568 libdrm/build.sh		08/08/2022 07:53 AM	rk3568-buildroot						
31					px30		09/23/2023 08:18 AM	px30 -ubuntu	system					
30					rk3588		08/06/2022 12:49 AM	rk3588 android						
28					rk3588 ubuntu v4l2, LIBJPEG_8.0		08/10/2022 01:28 AM	rk3588 ubuntu						
27					rk3588		08/05/2022 09:34 AM	rk3588 ubuntu	system					
26					t113		08/05/2022 06:32 AM	t113 -buildroot						
25					t507 linux		08/05/2022 11:43 AM	t507-ubuntu	touch					
23					rk3288 usb-5v 2v		08/03/2022 11:17 AM	rk3288						
22					px30 QT		08/04/2022 06:38 AM	px30 -ubuntu				0.00		
29					px30 qt qml		08/05/2022 06:26 AM	px30 -ubuntu		#22: px30 QT	px30 QT			
21					rk3568 npu		09/19/2022 02:12 AM	rk3568-buildroot	NPU					
19					rk3328 otg host		08/05/2022 09:36 AM	rk3328-ubuntu	ota /sd /update					
18					rv1126 ov13850		08/03/2022 09:29 AM	rv1126-buildroot	sensor					
17					rv1126 Linux ISP		08/05/2022 10:02 AM	rv1126-buildroot	isp					
16					rk3588		08/08/2022 08:30 AM	rk3588 android	display			0.00		
46					rk3588 RkVideoPlayer-8.1+(8.1) rtsp		08/09/2022 01:14 AM	rk3588 android		#16: rk3588	rk3588			
15					rk3588 ubuntu usb		08/05/2022 09:35 AM	rk3588 ubuntu	audio					
14					rk3588 isp		08/08/2022 07:14 AM	rk3588 ubuntu	isp					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
13					a40i mplayer		08/18/2022 12:21 AM	a40i-buildroot	display					
12					rk3588 ping		09/27/2022 04:38 AM	rk3588 ubuntu						
11					hi3516dv 300 3.3v		08/05/2022 10:06 AM	hi3516dv300_v20						
10					t113 ping		12/01/2022 07:23 AM	t113 -buildroot						
9					rk3399 ov13850		08/16/2022 09:24 AM	rk3399-ubuntu	sensor					
7					rv1126 buildroot IP		07/13/2023 05:54 AM	rv1126-buildroot						
6					t113 Ubuntu ssh		10/14/2022 07:19 AM	t113 -buildroot	ssh					