

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimate d time	Last updated by	Related issues
259					3128		04/07/2024 07:59 AM	rk3128-android	system					
258					rk3568 android11		04/07/2024 06:41 AM	rk3568-android	system					
257					rv1126		03/27/2024 12:10 AM	rv1126-ubuntu	system					
256					rk3588		03/25/2024 04:22 AM	rk3588 ubuntu	display					
255					rk3588 Android13		03/18/2024 06:54 AM	rk3588 android	system					
254					PRO-RK3568-AHD-V11		03/16/2024 09:07 AM	rk3568-android	rtc					
253					rk1808 rtc		03/08/2024 07:07 AM	rk1808-buildroot	rtc					
251					rv1126 lane in		03/07/2024 07:22 AM	rv1126-buildroot	audio					
250					a133		03/06/2024 08:21 AM	a133-android						
249					a311d		02/20/2024 02:27 AM	a311d-android	audio					
248					a133		02/19/2024 06:12 AM	a133-android	system					
247					rk3588 buildroot pwr		02/20/2024 08:47 AM	rk3588-buildroot	system					
246					rv1109-rv1126 Ubuntu20.04		01/19/2024 05:02 AM	rv1126-ubuntu						
245					linux5.10 qt		02/27/2024 11:16 PM	rk3568-buildroot	system					
243					3568 Android		01/05/2024 08:49 AM	rk3568-android						
242					ubuntu20.04		01/04/2024 01:43 AM	rk3588 ubuntu						
241					rp3128 OTA		12/29/2023 07:43 AM	rk3128-buildroot						
239					t509 Android		12/23/2023 08:34 AM	t509 -android10						
238					rk3588 ubuntu20.04		12/17/2023 11:53 PM	rk3588 ubuntu	display					
237					3588		12/14/2023 06:36 AM	rk3588-buildroot	audio					
236					3588 buildroot		12/09/2023 04:53 AM	rk3588-buildroot						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
232					rk3568 buildroot demo		11/23/2023 02:16 AM	rk3568-buildroot						
230					rk1808 dt8912 dsi hdmi mipi		11/18/2023 07:03 AM	rk1808-buildroot	display					
229					RP-BOX-RK3399 Android APP		11/07/2023 01:00 AM	rk3399 -android						
228					pro-box-t507		11/05/2023 11:29 PM	t507-ubuntu						
227					rd-rk3588 pcie		11/01/2023 11:56 PM	rk3588 ubuntu	pcie					
226					linux4.19 sdk linux5.10 sdk		10/29/2023 11:32 PM							
225					rk3568 ubuntu20.04		10/27/2023 12:19 AM	rk3568-ubuntu	system					
224					1106 IPC media Sample		10/19/2023 09:12 AM	rv1106						
223					rk3588 linux hdmi		03/06/2024 04:10 AM	rk3588-buildroot	display					
222					t507 linux		10/19/2023 12:01 AM	t507	touch					
221					rk3328 linux		11/04/2023 07:45 AM	rk3328-buildroot	system					
220					rk3588 ubuntu 20.04		09/28/2023 09:20 AM	rk3588 ubuntu						
219					3308 mic uac		09/28/2023 09:49 AM	rk3308-buildroot	audio					
218					RK3308 mic		09/28/2023 07:18 AM	rk3308-buildroot	audio					
217					rk3588 ubuntu20.04 NoMachine		09/28/2023 05:35 AM	rk3588 ubuntu	system				wu wu	
216					rk3568 android 4g		02/22/2024 02:30 AM	rk3568-android						
215							09/26/2023 11:26 PM							
214					rk3588 ubuntu 20.04 gcc		09/20/2023 07:31 AM	rk3588 ubuntu	system					
213					rk3568 rtc		09/20/2023 10:37 AM	rk3568-ubuntu	rtc					
212					rk3588 isp		11/29/2023 01:23 AM	rk3588-buildroot	sensor					
211					rk3588 linux wifi		09/02/2023 06:06 AM	rk3588-debian	wifi					
210					rk3588 i2s		08/31/2023 12:01 AM	rk3588-buildroot	audio					
208					rk3568 mic		07/27/2023 02:17 AM	rk3568-buildroot	audio					
207					rv1126		07/23/2023 11:55 PM	rv1126-buildroot						
206					1106 web sd		07/22/2023 01:15 AM	rv1106	system					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
205					rk3588 uboot LPDDR4		11/01/2023 11:56 PM	rk3588 ubuntu						
204					t113 i2c1		06/15/2023 12:21 AM	t113 -buildroot						
203					rk3588 ubuntu20.04 qt		11/29/2023 02:23 AM	rk3588 ubuntu	system					
202					rk3588 android		05/13/2023 06:09 AM	rk3588 android	wifi					
201					rk3399 android ota		05/09/2023 05:28 AM	rk3399 -android	ota /sd /update					
200					t113 type-C otg usb_id_gpio		04/17/2023 11:51 AM	t113 -buildroot						
199					s905d3 wifi		04/13/2023 05:48 AM	s905d3-android	wifi					
198					rk3588 GPU		09/25/2023 08:00 AM	rk3588 ubuntu	gpu					
197					rk3399		03/28/2023 11:33 AM	rk3399-buildroot	system					
196					rv1106 type-c adb		03/29/2024 12:48 AM	rv1106						
195					rk3588 edp		03/15/2023 11:40 AM	rk3568-ubuntu	display					
194					t507 wifi		03/15/2023 03:16 AM	t507-ubuntu	wifi					
193					rv1126 logo		03/11/2023 05:56 AM	rv1126-ubuntu						
192					rk3568		03/09/2023 04:57 AM	rk3568-android						
191					rk3568 linux		03/08/2023 06:13 AM	rk3568-ubuntu	display					
190					t113 4g		03/07/2023 04:30 AM	t113 -buildroot						
189					t507 GPIO dts		03/04/2023 01:31 AM	t507-ubuntu	gpio					
188					rk3588 usb		03/03/2023 10:37 AM	rk3588 android	display					
187					rk3288 8.1 32		03/04/2023 06:50 AM	rk3288	uart					
186					rk3588 debian docker		02/18/2023 07:49 AM	rk3588-debian						
185					rv1126 sdk		02/11/2023 02:19 AM	rv1126-ubuntu						
184					rk3588 hdmi		03/15/2023 03:39 AM	rk3588 ubuntu	display					
183					rk3588 android12		01/13/2023 06:23 AM	rk3588 android						
181					rk3588 app		01/10/2023 10:40 AM	rk3588 android	system					
180					rk3568 qt		01/10/2023 01:58 AM	rk3568-ubuntu						
179					t113 pwm		07/14/2023 01:14 AM	t113 -buildroot	pwm					
177					rv1126		01/09/2023 12:40 AM	rv1126-ubuntu	system					
175					t507		05/25/2023 04:59 AM	t507-ubuntu						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
174					rk3328 hdmi		01/02/2023 05:58 AM	rk3328-ubuntu	display					
172					rk3568 usr/bin/startlxde		12/30/2022 12:47 AM	rk3568-ubuntu	display					
171					rk3399 android8.1 apk		09/16/2023 07:09 AM	rk3399 -android						
170					t507 android		12/28/2022 07:31 AM	t509 -android10						
168					rv1126 isp		12/26/2022 08:19 AM	rv1126-buildroot	display					
167					rk3566 echo 1000 > phy_lb_scan		08/17/2023 07:35 AM	rk3566-buildroot						
166					rk3328 wifi		12/15/2022 08:01 AM	rk3328-buildroot	wifi/					
165					rk3568		12/14/2022 06:48 AM	rk3568-ubuntu						
164					t509		12/14/2022 01:15 AM	t509 -android10						
163					rk3588 can canfd		07/30/2023 11:19 PM	rk3588 ubuntu	can					
162					rk3568 gpio		09/18/2023 04:43 AM	rk3568-buildroot	gpio					
161					rk3588		12/09/2022 05:07 AM	rk3588-debian	system					
160					rk3328 mac		12/15/2022 11:36 AM	rk3328-ubuntu	system					
159					rk3568 ptp1588		12/08/2022 05:37 AM	rk3568-buildroot						
158					rk3568 gpio		05/13/2023 05:02 AM	rk3568-buildroot	gpio					
157					rk3399pro docker rknn		12/05/2022 01:15 AM	rk3399pro-linux	NPU					
156					rk3568 builroot python		11/29/2022 11:58 AM	rk3568-buildroot						
155					px 30 android8.1 ota		08/24/2023 06:45 AM	px30 -android						
154					a40i		11/26/2022 03:00 AM	a40i-buildroot						
153					t507 buildroot video		11/25/2022 11:28 AM	t507	system					
152					rk3588		11/23/2023 12:46 AM	rk3588 ubuntu						
151					rk3566 ubunt rknn		11/25/2022 12:49 AM	rk3566-ubuntu	NPU					
150					rk3588 rk		11/15/2022 07:52 AM	rk3588-debian						
149					rk3588 ip		11/11/2022 11:04 AM	rk3588-buildroot						
148					rk1808 ntp		11/09/2022 10:56 AM	rk1808-buildroot	NPU					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
147					RK3399 Rtmp		11/02/2022 07:55 AM	rk3399-ubuntu	wifi					
146					t972 hdmi in		10/31/2022 11:28 AM	t972-android9.0	display					
145					a311d2		11/10/2022 12:07 AM	A311D2-android	sensor					
144					rk3288 linux		08/14/2023 07:22 AM	rk3288						
143					rk1808 RNDIS		10/28/2022 05:59 AM	rk1808-buildroot						
142					Rk3128		03/29/2023 08:52 AM	rk3128-buildroot						
139					rv1126		10/24/2022 04:43 AM	rv1126-buildroot						
138					px30		10/24/2022 01:31 AM	px30-android	system					
137					rk3568		01/02/2024 04:59 AM	rk3568-ubuntu						
136					rk3399 gps		10/20/2022 06:21 AM	rk3399-android						
135					rv1126 pip		10/14/2022 12:16 PM	rv1126-ubuntu						
134					rk3399 4G		10/14/2022 05:41 AM	rk3399-ubuntu						
133					px30 log		10/13/2022 11:55 AM	px30-buildroot	system					
132					T507 "POP"		12/02/2023 07:36 AM	t507	audio					
131					rk3399 android8.1 adb		10/10/2022 11:57 AM	rk3399-android						
130					rk3399 android		10/09/2022 12:35 AM	rk3399-android	display					
129					rv1126 uvcsdk		09/27/2022 08:52 AM	rv1109-buildroot	sensor					
128					rk3399		09/28/2022 10:36 AM	rk3399-ubuntu	system					
127					rk3568		09/23/2022 02:24 AM	rk3568-ubuntu	system					
125					rk3588 5g		09/21/2022 06:17 AM	rk3588 android						
124					t507		09/17/2022 06:33 AM	t507-ubuntu	gpio					
123					rk3588 v4l2 gain control		10/07/2023 11:49 PM	rk3588-debian	sensor					
122					rk3588 buildroot egl		09/16/2022 09:11 AM	rk3588-buildroot						
121					rk3588		09/16/2022 06:50 AM	rk3588 ubuntu						
120					rv-1126		03/10/2023 01:17 AM	rv1126-buildroot	touch					
119					rk3588 usb3.0		09/15/2022 12:36 AM	rk3588 ubuntu	display					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
118					rk3568 mmm		09/13/2022 09:33 AM	rk3568-android						
116					rk3566 gpio		09/12/2023 07:24 AM	rk3566-android	gpio					
115					rk3588 hdmi rx		08/31/2023 05:50 AM	rk3588 ubuntu	display					
114					rk3566 ubuntu adb		09/27/2023 04:37 AM	rk3566-ubuntu	system					
113					px30 apk		09/02/2022 06:50 AM	px30 -android						
112					rk3568 pcie2.0		11/29/2023 05:01 AM	rk3568-buildroot	pcie					
111					rv1126 can		09/16/2022 09:01 AM	rv1126-buildroot	can					
110					rk3588 android ip		09/16/2022 07:31 AM	rk3588 android						
109					rv1126k 4G usb		09/05/2022 08:21 AM	rv1126-buildroot						
108					rk3399pro		08/31/2022 08:31 AM	rk3568-buildroot	system					
107					t113 buildroot		03/06/2023 07:57 AM	t113 -buildroot	system					
105					rk3128 pwm2		08/30/2022 07:10 AM	rk3128-android	pwm					
103					6818 mac		09/07/2022 05:36 AM	6818-android						
102					rk3588 ubuntu 18.04 rtc		08/26/2022 08:50 AM	rk3588 ubuntu	rtc					
101					t113		08/26/2022 06:02 AM	t113 -buildroot	gpio					
100					t113 can		02/08/2023 06:20 AM	t113 -buildroot	can					
99					rk1808 npu		10/12/2022 07:38 AM	rk1808-buildroot	NPU					
98					rk3588 uboot		11/09/2023 06:33 AM	rk3588-debian	system					
97					rv1126 rv1109		08/25/2022 10:57 AM	rv1109-buildroot						
96					rk3568 linux debug		06/14/2023 07:29 AM	rk3568-buildroot						
95					t113		02/22/2023 04:43 AM	t113 -buildroot						
94					px30 log		08/23/2022 08:24 AM	px30 -android	display					
93					rk3399 emmc		08/22/2022 11:21 AM	rk3399-buildroot						
92					rv1126 gstreamer		08/22/2022 09:02 AM	rv1126-buildroot						
91					rk3399 ubuntu		08/22/2022 07:26 AM	rk3399-ubuntu	system					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
89					rk3568 pcie2.0 fpga		08/22/2022 10:27 AM	rk3568-buildroot	pcie					
88					rk3588 androidDP		08/22/2022 02:44 AM	rk3588 android	display					
87					rk3399		10/11/2022 12:53 AM	rk3399 -android						
86					rv1126 uboot		12/08/2023 05:46 AM	rv1126-ubuntu	system					
85					rk3588 hdmi		08/23/2022 01:37 AM	rk3588-buildroot	display					
84					rk 3588 mpp		10/23/2023 06:38 AM	rk3588-debian						
83					rk3588 linux rtsp demo		08/19/2022 05:45 AM	rk3588						
82					rk3588 hdmi		08/20/2022 03:00 AM	rk3588 ubuntu	display					
81					rk3588 dtb,dtc		08/18/2022 02:15 AM	rk3588 ubuntu						
80					rk3308		08/18/2022 01:08 AM	rk3308-buildroot	system					
79					rk3399 edp		08/19/2022 08:21 AM	rk3399	display					
78					rk3568 i2s3		04/19/2023 05:49 AM	rk3568-ubuntu						
68					rk3128 uvc		08/16/2022 09:15 AM	rk3128-android	sensor					
65					rk3588 ubuntu18.04 OpenCV3.4.6+opencv_contrib 3.4.6		01/03/2023 12:06 PM	rk3588 ubuntu						
64					rk3588 ubuntu 18.04 demo		08/17/2022 01:16 AM	rk3588 ubuntu						
61					rk3568 buildroot i2c m0 m1		08/10/2022 07:26 AM	rk3568-buildroot	I2C					
59					t507		08/12/2022 12:12 PM	t507-ubuntu	gpio					
55					rk3588 linux		08/09/2022 09:42 AM	rk3588						
45					rk3568		08/08/2022 09:17 AM	rk3568-buildroot						
44					rk3568 4G		08/19/2022 07:46 AM	rk3568-android						
41					rk3399 ubuntu 16.04		08/09/2022 10:17 AM	rk3399-ubuntu						
38					rv1126 gpio		08/06/2022 02:48 AM	rv1126-buildroot	gpio					
26					t113		08/05/2022 06:32 AM	t113-buildroot						
23					rk3288 usb-5v 2v		08/03/2022 11:17 AM	rk3288						
22					px30 QT		08/04/2022 06:38 AM	px30 -ubuntu				0.00		

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
19					rk3328 otg host		08/05/2022 09:36 AM	rk3328-ubuntu	ota /sd /update					
18					rv1126 ov13850		08/03/2022 09:29 AM	rv1126-buildroot	sensor					
15					rk3588ubuntuusb		08/05/2022 09:35 AM	rk3588 ubuntu	audio					
37					px30 gpio		08/09/2022 07:56 AM	px30 -android	gpio					
77					rk3568 hdmi		08/16/2022 06:07 AM	rk3568-ubuntu	display					
71					ov13850		08/16/2022 08:34 AM	sensor	sensor					
66					sdk npu 1.7		08/11/2022 08:52 AM	rk3399 -android	NPU					
53					rk3588 ubuntu V4l2 4AHD		10/19/2023 04:48 AM	rk3588 ubuntu	sensor					
52					rk3399 20		08/24/2022 12:09 AM	rk3399 -android	system					
51					rv1126		08/09/2022 05:21 AM	rv1126-buildroot						
50					rv1126 buildroot glibc		08/09/2022 02:22 AM	rv1126-buildroot						
49					rk3588 rd-rk3588.dts		08/08/2022 11:02 AM	rk3588						
46					rk3588 RkVideoPlayer-8.1+(8.1)rtsp		08/09/2022 01:14 AM	rk3588 android		#16: rk3588	rk3588			
40					rk3588 cmake-qt-gui update		08/06/2022 06:10 AM	rk3588						
39					rk3566 adb		09/02/2022 11:13 AM	rk3566-android						
36					t507linux		08/06/2022 06:45 AM	t507-ubuntu						
35					rv1109 buildroot		08/05/2022 10:01 AM	rv1109-buildroot	system					
34					rv1126 imx415		08/09/2022 05:25 AM	rv1126-buildroot	sensor					
32					rk3568 libdrm build.sh		08/08/2022 07:53 AM	rk3568-buildroot						

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
29					px30 qt qmi		08/05/2022 06:26 AM	px30 -ubuntu		#22: px30 QT	px30 QT			
27					rk3588		08/05/2022 09:34 AM	rk3588 ubuntu	system					
25					t507 linux		08/05/2022 11:43 AM	t507-ubuntu	touch					
13					a40i mplayer		08/18/2022 12:21 AM	a40i-buildroot	display					
244					rk3568 rga imcvtcolor rga		01/15/2024 07:29 AM	rk356x						
240					t113 rs485		12/23/2023 02:05 AM	t113 -buildroot						
235					a311d ubuntu20.04 QT		12/23/2023 02:05 AM							
234					gpio uboot gpio		12/04/2023 04:26 AM	rk3588-buildroot	gpio					
233					t507		12/04/2023 12:28 AM	t507-ubuntu	system					
231					rk3568 Openharmony 4.0		11/23/2023 12:20 AM	rk356x						
209					rk3588 linux5.10 can		01/11/2024 04:16 AM	rk3588 ubuntu	can					
182					rk3588 ubuntu 20.04 root		03/25/2023 06:15 AM	rk3588 ubuntu	system					
178					rk3288 android 8.1 wifi		01/07/2023 06:03 AM	rk3288						
176					rk3566 cpu		01/07/2023 06:03 AM	rk3566-buildroot						
173					rk		03/26/2024 09:17 AM	rk						
169					rk3568 android		01/07/2023 06:04 AM	rk3568-android	system					
141					rk3588 pc		10/26/2022 06:54 AM	rk3588-buildroot						
140					rv1126 spi0 m0 m1		10/26/2022 06:54 AM	rv1126-ubuntu						
126					rk3568 android		12/20/2023 01:15 AM	rk3568-ubuntu						
117					h6		09/08/2022 08:43 AM	h6 android	display					
106					rk3588 sd		01/30/2024 09:02 AM	rk3588 ubuntu	SD					
90					t507		08/22/2022 10:59 AM	t507-ubuntu						
76					rk3566 rk3566 rk3568		08/16/2022 02:22 AM	rk3566-android						
75					rk3568 sd		04/28/2023 12:46 AM	rk3568-buildroot	system					
74					rk3568 gpu		11/09/2022 11:28 AM	rk3568-buildroot	gpu					

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
73					rk3588 parameter.txt		08/15/2022 06:54 AM	rk3588-buildroot						
72					rk3588-4		08/15/2022 06:16 AM	sensor	sensor					
70					rv1109 ubuntu yoloV5		08/15/2022 05:15 AM	rv1109-ubuntu						
69					t507 mipi dsi , can2		08/13/2022 06:12 AM	t507						
67					rk3399pro android 9.0 adb		08/31/2022 09:17 AM	rk3399pro-android						
63					rk3566 v2 .v3		11/01/2023 12:04 AM	rk3566-android	display					
62					rk3588		10/23/2023 08:41 AM	rk3588	sensor					
60					rk3588		08/18/2022 12:18 AM	rk3588 ubuntu						
58					RK3288 Mipi		08/09/2022 11:45 AM	rk3288						
57					a311d2		08/10/2022 07:29 AM	A311D2-android						
56					a311d2		08/09/2022 10:15 AM	A311D2-android	wifi					
54					rk3568 linux mdio bus name?		08/09/2022 09:02 AM	rk3568-buildroot						
48					rv1126 -rv1109 809		08/08/2022 10:02 AM	rv1109-buildroot	audio					
43					rk3588 linux evb rk3588-linux-sdk-beat-v0.1.0 sdk		08/08/2022 07:44 AM	rk3588 ubuntu						
42					rk3588 multi		06/09/2023 09:00 AM	rk3588 ubuntu						
31					px30		09/23/2023 08:18 AM	px30 -ubuntu	system					
30					rk3588		08/06/2022 12:49 AM	rk3588 android						
28					rk3588 ubuntu v4l2 ,LIBJPEG_8.0		08/10/2022 01:28 AM	rk3588 ubuntu						
21					rk3568 npu		09/19/2022 02:12 AM	rk3568-buildroot	NPU					
17					rv1126 Linux ISP		08/05/2022 10:02 AM	rv1126-buildroot	isp					
16					rk3588		08/08/2022 08:30 AM	rk3588 android	display			0.00		

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Target version	Category	Parent task	Parent task subject	Total estimated time	Last updated by	Related issues
11					hi3516dv 300 3.3v		08/05/2022 10:06 AM	hi3516dv300_v20						
10					t113 ping		12/01/2022 07:23 AM	t113 -buildroot						
9					rk3399 ov13850		08/16/2022 09:24 AM	rk3399-ubuntu	sensor					
7					rv1126 buildroot IP		07/13/2023 05:54 AM	rv1126-buildroot						
6					t113 Ubuntu ssh		10/14/2022 07:19 AM	t113 -buildroot	ssh					
14					rk3588 isp		08/08/2022 07:14 AM	rk3588 ubuntu	isp					
12					rk3588 ping		09/27/2022 04:38 AM	rk3588 ubuntu						